



## An International System of Electrotherapeutics, for Students, General Practitioners, and Specialists

By -

RareBooksClub. Paperback. Book Condition: New. This item is printed on demand. Paperback. 28 pages. Original publisher: Washington, D. C. : National Transportation Safety Board, 2001 OCLC Number: (OCoLC)310647188 Subject: Aircraft accidents -- Illinois -- Chicago. Excerpt: . . . 15 WRECKAGE AND IMPACT INFORMATION Ground scars indicated that the airplane touched down 160 feet short of the runway pavement ( 314 feet from the runways displaced threshold ), became airborne, touched down again on the runway, and then slid about 2, 350 feet down the runway until coming to rest in an upright position in the mud about 250 feet to the right ( west ) of the runway. The two main landing gears and parts of the airplanes lower aft section and left and right wings were found along a 2, 670-foot debris path, beginning before the runway threshold and ending where the airplane came to rest. The nose landing gear was found rotated aft into the electrical electronics ( E E ) compartment. The pneumatic start connection door and the lower tail skid assembly from the aft fuselage were found 180 feet from the runway threshold. The airstairs, airstairs door, right spoiler panels, flap surfaces and control assemblies,...



**READ ONLINE**  
[ 9.66 MB ]

### Reviews

*Extensive manual! Its this type of great read through. Sure, it is actually engage in, nonetheless an interesting and amazing literature. Its been written in an exceedingly simple way and it is simply right after i finished reading this pdf through which basically altered me, affect the way i believe.*

-- **Mrs. Mertie Cummerata**

*This is an amazing book that I actually have actually read through. I am quite late in start reading this one, but better then never. You will not truly feel monotony at anytime of the time (that's what catalogs are for concerning should you ask me).*

-- **Scottie Schroeder DDS**