



## Care and operation of the caterpillar 75 tractor

By Holt Manufacturing Company

RareBooksClub. Paperback. Book Condition: New. This item is printed on demand. Paperback. 34 pages. Dimensions: 9.7in. x 7.4in. x 0.1in. This historic book may have numerous typos and missing text. Purchasers can download a free scanned copy of the original book (without typos) from the publisher. Not indexed. Not illustrated. 1917 Excerpt: . . . Xo. 5 on carbon and carbon troubles. Valves Must Operate Correctly To secure a perfect carbureter adjustment, the valves must seat perfectly and open and close correctly. Before proceeding with the carbureter adjustment it is absolutely necessary to be sure that when the cam is disengaged on each particular valve rod guide, all the slack is taken up on the valve tappet, valve rod and rocker arm. so that the rocker arm has a clearance of one thirtysecond of an inch over the valve stem. This distance must not be varied. 156 Fig. 18 shows a diagram of the cam, valve rod and rocker arm giving a clear-ance of one thirty-second of an inch over the valve stem when the cam is pointing downwards. Carbureter adjustment can be interfered with very readily and the engine can lose power if the clearance is greater or less than...

DOWNLOAD



READ ONLINE

[ 7.06 MB ]

### Reviews

*This sort of book is almost everything and helped me looking in advance and much more. Yes, it can be enjoy, nevertheless an amazing and interesting literature. Its been written in an extremely simple way which is simply right after i finished reading this publication through which in fact altered me, alter the way i really believe.*

-- **Lizeth Witting**

*This composed pdf is excellent. We have go through and that i am certain that i am going to likely to read again once more down the road. I am just happy to explain how this is basically the very best publication i have go through within my own daily life and can be he best publication for actually.*

-- **Anika Kertzmann**